

Figure 2: Topographic Map Locating the Project Site






Figure 5: Eroding bank on the [redacted] Property on Richland Creek



Figure 6: View from top of the eroding bank on the [redacted] property on Richland Creek





Figure 7: Photo of upstream end of eroding site on [redacted] property on Richland Creek.



Figure 8: Photo of eroding site on [redacted] property on Richland Creek from the point bar opposite the bank.

